

# TOOLING SYSTEM Tap Chuck

## Air tapping spindle 氣動攻牙機

絲攻夾頭

C-21



- ▷ Air tapping spindle
- ▷ Parallel arm
- ▷ Table mounting column
- ▷ Air unit
- ▷ Complete specifications

- ▷ 氣動攻牙機主軸
- ▷ 伸長臂
- ▷ 固定座
- ▷ 三點組合
- ▷ 規格齊全

Code No. 型號	Type 規格	Capacity 攻牙能力	Spindle R.P.M 主軸轉速	Work Place 工作範圍
SMB0001	SW-0708	M8	700 R.P.M	Rmax 700 mm
SMB0002	SW-0712	M12	400 R.P.M	
SMB0003	SW-0716	M16	250 R.P.M	
SMB0004	SW-0720	M20	200 R.P.M	
SMB0005	SW-0722	M22	200 R.P.M	
SMB0006	SW-0724	M24	100 R.P.M	
SMB0007	SW-1408	M8	700 R.P.M	Rmax 1400 mm
SMB0008	SW-1412	M12	400 R.P.M	
SMB0009	SW-1416	M16	250 R.P.M	
SMB0010	SW-1420	M20	200 R.P.M	
SMB0011	SW-1422	M22	200 R.P.M	
SMB0012	SW-1424	M24	100 R.P.M	
SMB0013	SW-1608	M8	700 R.P.M	Rmax 1600 mm
SMB0014	SW-1612	M12	400 R.P.M	
SMB0015	SW-1616	M16	250 R.P.M	
SMB0016	SW-1620	M20	200 R.P.M	
SMB0017	SW-1622	M22	200 R.P.M	
SMB0018	SW-1624	M24	100 R.P.M	
SMB0019	SW-1908	M8	700 R.P.M	Rmax 1900 mm
SMB0020	SW-1912	M12	400 R.P.M	
SMB0021	SW-1916	M16	250 R.P.M	
SMB0022	SW-1920	M20	200 R.P.M	
SMB0023	SW-1922	M22	200 R.P.M	
SMB0024	SW-1924	M24	100 R.P.M	